


T5020 to C2020 Mirror Wiring Diagram



To mirror to the C2020, you must first connect a wire between the output of the master device to the input of the device you wish to read the same as the master.

Then connect the power from the master device to the slave device, using two wires, seen as red and black in the diagram. This then needs to connect to the power supply.

Either gauge can be powered from the power supply first

Power Supply

Units are supplied with either 24vdc direct connection, or 100/240 Vac power supply.

Power supply connection can be made by removing the removing the mounting bracket screws temporarily